


**SUBMITTAL TO THE BOARD OF SUPERVISORS  
COUNTY OF RIVERSIDE, STATE OF CALIFORNIA**

2178



**FROM:** County Counsel/TLMA  
Code Enforcement Department

**SUBMITTAL DATE:**  
March 4, 2010

**SUBJECT:** Abatement of Public Nuisance [Substandard Structures, Excess Outside Storage and Accumulation of Rubbish];  
Case No.: CV 07-9901; HOANG  
Subject Property: 14545 Chandler Street, Corona; APN: 144-120-009  
District Two

**RECOMMENDED MOTION:** Move that:

- (1) The substandard structures (single family dwelling with attached garage, carport and five room additions) on the real property located at 14545 Chandler Street, Corona, Riverside County, California, APN 144-120-009 be declared a public nuisance and a violation of Riverside County Ordinance No. 457 which does not permit substandard structures on the property.
- (2) Kevin Hoang, the owner of the subject real property, be directed to abate the substandard structures on the property by rehabilitating, removing and/or demolishing the same from the real property, including the removal and disposal of all structural debris and materials, within ninety (90) days.

(Continued)

*[Signature]*  
\_\_\_\_\_  
JULIE A. JARVI, Deputy County Counsel  
for PAMELA J. WALLS, County Counsel

<b>FINANCIAL DATA</b>	Current F.Y. Total Cost:	\$ N/A	In Current Year Budget:	N/A
	Current F.Y. Net County Cost:	\$ N/A	Budget Adjustment:	N/A
	Annual Net County Cost:	\$ N/A	For Fiscal Year:	N/A

<b>SOURCE OF FUNDS:</b>	Positions To Be Deleted Per A-30	<input type="checkbox"/>
	Requires 4/5 Vote	<input type="checkbox"/>

**C.E.O. RECOMMENDATION:**

APPROVE

BY: *[Signature]*  
Tina Grande

County Executive Office Signature

Dept't Recomm.:  Consent  Policy

Per Exec. Ofc.:  Consent  Policy

Prev. Agn. Ref.: \_\_\_\_\_ District: 2 Agenda Number: \_\_\_\_\_

- (3) The owner be ordered to ascertain the existence or non-existence of asbestos containing materials in said structures by survey and materials sample testing through the Industrial Hygiene Specialist of the County Health Department, Division of Special Services; and, prior to the abatement ordered in paragraph number two (2) above, to secure the removal and disposal of all asbestos containing materials discovered through such survey and testing by contract with a duly certified and licensed contractor for the handling of such materials to avoid citations and/or fines imposed by the South Coast Air Quality Management District (SCAQMD) pursuant to SCAQMD Rule No. 1403.
- (4) The excess outside storage and accumulation of rubbish on the real property located at 14545 Chandler Street, Corona, be declared a public nuisance and a violation of Riverside County Ordinance Nos. 348 and 541 which do not permit the excess outside storage and accumulation of rubbish on the property.
- (5) Kevin Hoang, the owner of the subject property, be directed to abate the excess outside storage and accumulation of rubbish on the property by removing and disposing of the same from the real property within ninety (90) days.
- (6) If the owner of the real property does not take the above described action within ninety (90) days of the date of the Board's Order to Abate, that representatives of the Code Enforcement Department, Sheriff's Department, and/or a contractor, upon consent of the owners, receipt of a Court Order authorizing entry onto the real property, or other authorization as provided by law, shall abate the substandard structure and the excess outside storage and accumulation of rubbish by removing and disposing of the same from the real property
- (7) The reasonable cost of the abatement, after notice and an opportunity for hearing, shall be imposed as a lien on the real property, which may be collected as a special assessment against the real property pursuant to Government Code Section 25845 and Ordinance No. 725.
- (8) County Counsel be directed to prepare the necessary Findings of Fact and Conclusions of Law that the substandard structure on the real property and the excess outside storage and accumulation of rubbish are declared to be in violation of Riverside County Ordinance Nos. 348, 457 and 541 and constitute a public nuisance. Further, County Counsel shall prepare an Order to Abate for approval by the Board.

**JUSTIFICATION:**

1. An initial inspection was made of the subject real property by the Code Enforcement Officer on May 7, 2009.
2. The inspection revealed substandard structures (single family dwelling with attached garage, carport and five room additions) on the subject real property in violation of Riverside County Ordinance No. 457. The substandard conditions of the structure included, but were not limited to the following: lack of or improper water closet, lavatory, bathtub, shower, or kitchen sink; lack of hot and cold running water to plumbing fixtures; hazardous wiring; members of walls, partitions or other vertical supports

that split, lean, list or buckle due to defective material or deterioration; members of ceilings, roofs, ceiling and roof supports or other horizontal members which sag, split or buckle due to defective material or deterioration; dampness of habitable rooms, faulty weather protection; general dilapidation or improper maintenance; public and attractive nuisance.

The inspection also revealed the excess outside storage and accumulation of rubbish (approximately 1,034 square feet) on the subject property in violation of Riverside County Ordinance No. 541. The excess outside storage and accumulation of rubbish consisted of, but was not limited to the following materials: rocks, trash, wood, household trash, mattresses, furniture, drywall, cinder blocks, toys and miscellaneous debris.

3. Subsequent inspections of the above-described real property on June 24, 2009, October 1, 2009, and February 11, 2010, revealed that the property continues to be in violation of Riverside County Ordinance Nos. 457 and 541.
4. Staff and the Code Enforcement Department have complied with the requirements set forth in the appropriate laws of this jurisdiction pertaining to the Administrative Abatement Proceedings for substandard structures, excess outside storage and accumulation of rubbish.