

**SUBMITTAL TO THE BOARD OF SUPERVISORS
COUNTY OF RIVERSIDE, STATE OF CALIFORNIA**

2083



FROM: County Counsel/TLMA
Code Enforcement Department

SUBMITTAL DATE:
September 15, 2011

SUBJECT: Abatement of Public Nuisance [Substandard Structure]
Case No. : CV 10-01616 [IANNITTI]
Subject Property: 33620 Naranjo St., Lake Elsinore; APN: 383-183-025
District: One

RECOMMENDED MOTION: Move that:

1. The one (1) substandard structure on the real property located at 33620 Naranjo St., Lake Elsinore, Riverside County, California, APN: 383-183-025 be declared a public nuisance and a violation of Riverside County Ordinance No. 457 which does not permit substandard structures on the property.
2. Elise Iannitti, the owner of the subject real property or whoever has possession or control of the premises, be directed to abate the substandard structure on the property by removing the same from the real property within ninety (90) days.

Departmental Concurrence

L. Alexandra Fong

(Continued)

L. ALEXANDRA FONG, Deputy County Counsel
for PAMELA J. WALLS, County Counsel

FINANCIAL DATA	Current F.Y. Total Cost:	\$ N/A	In Current Year Budget:	N/A
	Current F.Y. Net County Cost:	\$ N/A	Budget Adjustment:	N/A
	Annual Net County Cost:	\$ N/A.	For Fiscal Year:	N/A

SOURCE OF FUNDS:	Positions To Be Deleted Per A-30	<input type="checkbox"/>
	Requires 4/5 Vote	<input type="checkbox"/>

C.E.O. RECOMMENDATION: APPROVE

BY: *Tina Grande*
Tina Grande

County Executive Office Signature

- Policy
- Consent
- Policy
- Consent

Dept't Recomm.:
Per Exec. Ofc.:

Prev. Agn. Ref.: District: 1 Agenda Number:

ATTACHMENTS FILED
WITH THE CLERK OF THE BOARD

9.1

Abatement of Public Nuisance
Case No.: CV 10-01616 [IANNITTI]
33620 Naranjo St., Lake Elsinore
APN# 383-183-025
District One
Page 2

3. The owner be ordered to ascertain the existence or non-existence of asbestos containing materials in said structure by survey and materials sample testing through the Industrial Hygiene Specialist of the County Health Department, Division of Special Services; and, prior to the abatement ordered in paragraph number two (2) above, to secure the removal and disposal of all asbestos containing materials discovered through such survey and testing by contract with a duly certified and licensed contractor for the handling of such materials to avoid citations and/or fines imposed by the South Coast Air Quality Management District (SCAQMD) pursuant to SCAQMD Rule No. 1403.
4. If the owner or whoever has possession or control of the real property does not take the above described action within ninety (90) days of the date of the Board's Order to Abate, that representatives of the Code Enforcement Department, Sheriff's Department, and/or a contractor, upon consent of the owner or receipt of a Court Order authorizing entry onto the real property when necessary under applicable law, may abate the substandard structure and contents therein, by removing the same from the real property.
5. The reasonable costs of abatement, after notice and an opportunity for hearing, shall be imposed as a lien on the real property, which may be collected as a special assessment against the real property pursuant to Government Code Section 25845 and Ordinance No. 725.
6. County Counsel be directed to prepare the necessary Findings of Facts and Conclusions that the substandard structure on the real property is declared to be in violation of Riverside County Ordinance No. 457 and a public nuisance, and further, to prepare an Order to Abate for approval by the Board.

BACKGROUND:

1. An inspection was made of the subject property by the Code Enforcement Officer on March 2, 2010. The inspection revealed one (1) substandard structure (dwelling) on the subject property in violation of Riverside County Ordinance No. 457 (RCC Title 15). The substandard conditions of the structure included, but were not limited to, the following: lack of improper water closet, lavatory, bathtub, shower or kitchen sink; lack of hot and cold running water to plumbing fixtures; hazardous wiring; lack of adequate heating facilities, deteriorated or inadequate foundation; defective or deteriorated flooring or floor supports; members of walls, partitions, or other vertical supports that split, lean, list or buckle due to defective material or deterioration; members of ceilings, roofs, ceiling and roof supports or other horizontal members which sag, split, or buckle due to defective material or deterioration; dampness of habitable rooms; faulty weather protection – deteriorated or ineffective weather proofing of exterior walls, roof or floors including broken windows or doors, lack of paint or other approved wall covering; general

dilapidation or improper maintenance; extensive fire damage; and public and attractive nuisance – abandoned and vacant.

2. Follow-up inspections on May 1, 2010, May 25, 2010, October 26, 2010, December 27, 2010, March 3, 2011, June 1, 2011 and August 25, 2011, revealed that the property continues to be in violation of Riverside County Ordinance No. 457.
3. Staff and the Code Enforcement Department have complied with the notice requirements set forth in the appropriate laws of this jurisdiction pertaining to the administrative abatement proceedings for substandard structure.